

Technical Note						
Reference:	TN20211118-01					
Version:	01.0	Category:	С			

MODEL(S)	GOAL	
All Evolution cart models	Quality improvement √	
	Performance	
	Upgrade √	
PARTS INFO	Down time √	
	Maintenance √	
New rear differential vent valve	Work around √	
	Others:	


VERSION CONTROL:					
Author:	Version:	Date:	Change/update:		
Arvin Lu	01.0	2022/11/08			

TITLE

How to solve the issue that differential oil leaks from the vent valve on the rear end.

How to do?

1. Replace the new vent valve on the rear end differential.



2.Reduce the amount of differential gear oil, the required amount is 650 ml (22 oz). The size of oil is GL-4 85W-90.

Evolution Electric Vehicle

www.evolutionelectricvehicle.com

Page | 1 of 1